

SERVICE




AOR
AGND
AI

DIGND
DI1
DI2
DI3
DI4

RS485-B
RS485-A

RS485-END



PWR

RUN




Digital outputs



Patron S107

RS232



1-wire



FBD
DO1
DO2
DO3
DO4
DOGND



RS485-A
RS485-B

RS485-END

GND
+24V